Flying Scot — Launch Checklist (Front)

From mast-up storage to floating at dock. Print double-sided (flip on short edge) for front/back cards.

1. Prepare parked boat for tow and launch

Check	Step	Description
	Hitch trailer	Coupler latched, pin in, safety chains on, jack up
	Remove cover	Take off and stow off ground to avoid ants
	Inspect rig	Mast, shrouds, forestay, spreaders, cotter pins/tape
	Halyards clear	Not wrapped around mast; run fair
	Sails secured	Flaked on boom/forestay with ties
	Main setup	Slugs in track, tack at gooseneck, clew to outhaul
	Jib setup	Hanks/furling secure; sheets led outside shrouds
	Mainsheet	Attached to traveler/bridle and boom
	Check spinnaker sheets	Spinnaker sheets installed properly and connected to spinnaker
	Check spinnaker halyard	Spinnaker halyard installed properly and connected to head of spinnaker
	Vang attached	Connected, slack for now
	Centerboard up	Uphaul secured; check for crank handle on board
	Install drain plug	Tighten now to avoid misses
	Load safety gear	Dock lines, fenders, PFDs, paddle, anchor, throwable, first aid
	Secure loose gear	Stow in cockpit or vehicle
	Walk-around	Final hazard and gear check; remove chocks

2. Ramp & launch

Check	Step	Description
	Park clear	Stay out of ramp traffic
	Dock lines & fenders	Attach lines fore/aft; fenders dock side
	Rudder up, halyards ready	Rudder locked up; halyards free; tiller stored on center (bungee or free sheet)
	Centerboard secured	Still up
	Wind check	Plan docking side and hoist angle
	Bow secured	Painter attached
	Apron pause	Last step on ramp: remove winch strap & safety chain, retain painter
	Back in until boat floats away	Trailer deep enough; crew retains control using painter
	Guide off	Use bow & stern lines
	Secure to dock	Fore and aft using cleat hitch

3. Final rigging afloat

Check	Step	Description
	Lower rudder blade	Secure downhaul
	Hoist main	Into wind; halyard, cunningham, outhaul set
	Remove mast supports	If used for storage
	Hoist jib	Set halyard tension for conditions
	Lower Centerboard	Lower slowely, make sure the line is free.
	Stow trailer gear	Back in the vehicle
	Safety check	Centerboard ready; sheets free; crew briefed

Departure tip: leave under main alone; hoist jib when clear and stable.

Flying Scot — Recovery & Storage Checklist (Back)

From sailing to mast-up storage, covered.

1. Approach & docking

Check	Step	Description
	Drop/furl jib early	Reduce power; improve visibility
	Check painter	Tie painter to front cleat if needed.
	Ease main to slow	Control speed, Button hook into wind and use sail as an air brake to control speed
	Luff alongside	Stop cleanly into wind
	Secure bow, then stern	Crew steps ashore with bow line, let boom out. Crew ties off using cleat hitch

2. De-rig at dock

Check	Step	Description
	Drop & flake main	Secure to boom, support boom using boom crutch
	Flake/furl jib	Tidy on forestay or furl
	Coil & secure lines	Sheets and halyards
	Rudder up & secure	Protect the blade
	Raise Centerboard	Use line to raise centerboard until tight, secure line in cleat.
	Fenders on	If not already hung

3. Load onto trailer

Check	Step	Description
	Retrieve trailer	Back down ramp straight
	Release dock lines	Keep bow line in hand
	Guide onto trailer	Walk with bow line; float on straight
	Winch to 8-12 inches slack	Leave enough slack in the winch line to allow the boat to rotate from partial float to level.
	Winch to bow stop	Once boat trailer is up on the level, crack winch to bow stop.Attach safety chain
	Pull clear of water	Stop on ramp apron
	Remove drain plug	Let water out before towing
	Rinse boat & trailer	If needed, and no one is waiting

4. Return to mast-up storage

Check	Step	Description
	Tow to storage	Drive carefully
	Chock trailer wheels	Prevent movement
	verify plug removed	Remove drain plug, stow in bow of trailer/boat up to ensure free drainage
	Remove loose gear	Vehicle or locker
	Inspect rigging	Note wear/damage
	Cover sails	Boom/mainsail cover; jib cover if used
	Install full boat cover	Secure straps/ties
	Final walk-around	Cover tight; nothing loose
	Unhitch trailer	Last step only